



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor


Ted Stewart
Executive Director

James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

October 11, 1994

TO: Minerals File

FROM: Lynn Kunzler, Reclamation Specialist 

RE: Site Inspection, Lamb, Sessions and Young Quarry, S/011/001, Davis County, Utah

Date of Inspection:	October 3, 1994
Time of Inspection:	2:30 pm
Conditions:	Intermittent snow and rain
Participants:	Lynn Kunzler, DOGM
Purpose of Inspection:	Document site conditions

No one else was present during this inspection. The SE1/4 of Section 29, T5N R1E in Weber Canyon was searched for evidence of this mining operation. No evidence was found of mining activity. On July 8, 1992, Mr. Tony Gallegos of the Division made an inspection of the area. The only disturbance he found was an old quarry that showed no signs of recent activity. It is possible that this site was never activated. The operator needs to be contacted to confirm status of the site.

S011001.94a